



iPod Release Notes V 3.0.0

- 1) SAAB Rear support added
- 2) Memory and track retention fixed from earlier versions on fast startup
- 3) BMW Random mode added. When in Random mode screen would not update correctly
- 4) BMW non-mp3 number of tracks updated correctly across pages
- 5) BMW mp3 improved folder browsing
- 6) BMW empty window now formatted correctly
- 7) Aux and audio source setting is now sticky across power downs
- 8) iPod unlock mode now sticky across power downs provided iPod remains plugged in
- 9) iPod pause on power down and resume on power up has now been added as a feature
- 10) BMW artists and title info work around for MASK head units software issue that caused info not to be displayed correctly
- 11) BMW non-idrive radio folder handling improved greatly to work around head unit software issues.
- 12) Configurable discs option been added as a feature allowing the user to switch disc settings out for another Genre through the disc 6 menus.
- 13) SAAB track select trigger added for folder browsing
- 14) Mercedes Audio 20 was not updating number of tracks correctly on fast startup

iPod Release Notes V 3.1.0 1st July 2008

- 1) BMW aux menu fixes for fast startup on professional radio
- 2) Bypass switch now requires a toggle of 5 times to go into valet mode. Also breaks the ring for 2 seconds.
- 3) BMW professional/mini set track when in aux mode no longer routes audio away to Pod
- 4) Configurable disc has extra check not allowing duplicate discs

iPod Release Notes V 3.2.0 24th June 2009

- 1) Audi iPod on fast startup was returning an error when not ready causing MMI to freeze up.
- 2) Audi number of tracks reported incorrectly occasionally now fixed.
- 3) Unlock mode wrap commands now increment and decrement correctly.
- 4) E65 BMW 2002-2005 models number of tracks reported incorrectly now fixed.
- 5) Mercedes Audio50 not playing iPod on plug-in from auxiliary menu
- 6) BMW play glitch when returning from auxiliary mode
- 7) Audi MMI3G compatibility added
- 8) Mercedes COMAND's booting to auxiliary menu now fixed from fast startup.